

## **UNIT-3 CORROSION & HEAT TREATMENT OF METALS AND ALLOYS**

Types of corrosion – effect of corrosion on mechanical properties – stress corrosion cracking – corrosion resistance materials used for space vehicles heat treatment of carbon steels – aluminium alloys, magnesium alloys and titanium alloys – effect of alloying treatment, heat resistance alloys – tool and die steels, magnetic alloys

### **CORROSION**

Corrosion is the deterioration of materials by chemical interaction with their environment. The term corrosion is sometimes also applied to the degradation of plastics, concrete and wood, but generally refers to metals. The most widely used metal is iron (usually as steel) and the following discussion is mainly related to its corrosion.

#### **THE CONSEQUENCES OF CORROSION**

The consequences of corrosion are many and varied and the effects of these on the safe, reliable and efficient operation of equipment or structures are often more serious than the simple loss of a mass of metal. Failures of various kinds and the need for expensive replacements may occur even though the amount of metal destroyed is quite small. Some of the major harmful effects of corrosion can be summarised as follows:

1. Reduction of metal thickness leading to loss of mechanical strength and structural failure or breakdown. When the metal is lost in localised zones so as to give a crack-like structure, very considerable weakening may result from quite a small amount of metal loss.
2. Hazards or injuries to people arising from structural failure or breakdown (e.g. bridges, cars, aircraft).
3. Loss of time in availability of profile-making industrial equipment.
4. Reduced value of goods due to deterioration of appearance.
5. Contamination of fluids in vessels and pipes (e.g. beer goes cloudy when small quantities of heavy metals are released by corrosion).
6. Perforation of vessels and pipes allowing escape of their contents and possible harm to the surroundings. For example a leaky domestic radiator can

cause expensive damage to carpets and decorations, while corrosive sea water may enter the boilers of a powerstation if the condenser tubes perforate.

7. Loss of technically important surface properties of a metallic component. These could include frictional and bearing properties, ease of fluid flow over a pipe surface, electrical conductivity of contacts, surface reflectivity or heat transfer across a surface.
8. Mechanical damage to valves, pumps, etc, or blockage of pipes by solid corrosion products.
9. Added complexity and expense of equipment which needs to be designed to withstand a certain amount of corrosion, and to allow corroded components to be conveniently replaced.

#### **CLASSIFICATION OF CORROSION:**

General Corrosion:	Localized Corrosion:	Metallurgically Influenced Corrosion:	Mechanically Assisted Degradation:	Environmentally Induced Cracking:
Corrosive attack dominated by uniform thinning <ul style="list-style-type: none"> <li>• Atmospheric corrosion</li> <li>• Galvanic corrosion</li> <li>• Stray-current corrosion</li> <li>• General biological corrosion</li> <li>• Molten salt corrosion</li> <li>• Corrosion in liquid metals</li> <li>• High – temperature corrosion</li> </ul>	High rates of metal penetration at specific sites <ul style="list-style-type: none"> <li>• Crevice corrosion</li> <li>• Filiform corrosion</li> <li>• Pitting corrosion</li> <li>• Localized biological corrosion</li> </ul>	Affected by alloy chemistry & heat treatment <ul style="list-style-type: none"> <li>• Intergranular corrosion</li> <li>• Dealloying corrosion</li> </ul>	Corrosion with a mechanical component <ul style="list-style-type: none"> <li>• Erosion corrosion</li> <li>• Fretting corrosion</li> <li>• Cavitation and water drop impingement</li> <li>• Corrosion fatigue</li> </ul>	Cracking produced by corrosion, in the presence of stress. <ul style="list-style-type: none"> <li>• Stress – Corrosion Cracking (SCC)</li> <li>• Hydrogen Damage</li> <li>• Liquid metal embrittlement</li> <li>• Solid metal induced embrittlement</li> </ul>

## CORROSION PREVENTION

By retarding either the anodic or cathodic reactions the rate of corrosion can be reduced. This can be achieved in several ways:

### 1. Conditioning the Metal

This can be sub-divided into two main groups:

(a) Coating the metal, in order to interpose a corrosion resistant coating between metal and environment. The coating may consist of:

- I. another metal, e.g. zinc or tin coatings on steel,
- II. a protective coating derived from the metal itself, e.g. aluminium oxide on “anodised” aluminium,

III. organic coatings, such as resins, plastics, paints, enamel, oils and greases.

The action of protective coatings is often more complex than simply providing a barrier between metal and environment. Paints may contain a corrosion inhibitor zinc coating in iron or steel confers cathodic protection.

(b) Alloying the metal to produce a more corrosion resistant alloy, e.g. stainless steel, in which ordinary steel is alloyed with chromium and nickel. Stainless steel is protected by an invisibly thin, naturally formed film of chromium sesquioxide  $\text{Cr}_2\text{O}_3$ .

## 2. Conditioning the Corrosive Environment

### (a) Removal of Oxygen


By the removal of oxygen from water systems in the pH range 6.5-8.5 one of the components required for corrosion would be absent. The removal of oxygen could be achieved by the use of strong reducing agents e.g. sulphite.

However, for open evaporative cooling systems this approach to corrosion prevention is not practical since fresh oxygen from the atmosphere will have continual access.

### (b) Corrosion Inhibitors


A corrosion inhibitor is a chemical additive, which, when added to a corrosive aqueous environment, reduces the rate of metal wastage. It can function in one of the following ways:

- (i) anodic inhibitors – as the name implies an anodic inhibitor interferes with the anodic process.



If an anodic inhibitor is not present at a concentration level sufficient to block off all the anodic sites, localised attack such as pitting corrosion can become a serious problem due to the oxidising nature of the inhibitor which raises the metal potential and encourages the anodic reaction (equation 1). Anodic inhibitors are thus classified as “dangerous inhibitors”. Other examples of anodic inhibitors include orthophosphate, nitrite, ferricyanide and silicates.

(ii) cathodic inhibitors – the major cathodic reaction in cooling systems is the reduction of oxygen.



There are other cathodic reactions and additives that suppress these reactions called cathodic inhibitors. They function by reducing the available area for the cathodic reaction. This is often achieved by precipitating an insoluble species onto the cathodic sites. Zinc ions are used as cathodic inhibitors because of the precipitation of  $\text{Zn}(\text{OH})_2$  at cathodic sites as a consequence of the localised high pH. Cathodic inhibitors are classed as safe because they do

not cause localised corrosion.

(iii) adsorption type corrosion inhibitors – many organic inhibitors work by an adsorption mechanism. The resultant film of chemisorbed inhibitor is then responsible for protection either by physically blocking the surface from the corrosion environment or by retarding the electrochemical processes. The main functional groups capable of forming chemisorbed bonds with metal surfaces are amino ( $-\text{NH}_2$ ), carboxyl ( $-\text{COOH}$ ), and phosphonate ( $-\text{PO}_3\text{H}_2$ ) although other functional groups or atoms can form co-ordinate bonds with metal surfaces.

(iv) mixed inhibitors – because of the danger of pitting when using anodic inhibitors alone, it became common practice to incorporate a cathodic inhibitor into formulated performance was obtained by a combination of inhibitors than from the sum of the individual performances. This observation is generally referred to a ‘synergism’ and demonstrates the synergistic action which exists between zinc and chromate ions.

### 3. Electrochemical Control

Since corrosion is an electrochemical process its progress may be studied by measuring the changes which occur in metal potential with time or with applied electrical currents. Conversely, the rate of corrosion reactions may be controlled by passing anodic or cathodic currents into the metal. If, for example, electrons are passed into the metal and reach the metal/electrolyte interface (a cathodic current) the anodic reaction will be stifled while the cathodic reaction rate increases. This

process is called cathodic protection and can only be applied if there is a suitable conducting medium such as earth or water through which a current can flow to the metal to be protected. In most soils or natural waters corrosion of steel is prevented if the potential of the metal surface is lowered by 300 or 400 mV. Cathodic protection may be achieved by using a DC power supply (impressed current) or by obtaining electrons from the anodic dissolution of a metal low in the galvanic series such as aluminium, zinc or magnesium (sacrificial anodes). Similar protection is obtained when steel is coated with a layer of zinc. Even at scratches or cut edges where some bare metal is exposed the zinc is able to pass protective current through the thin layer of surface moisture.

In certain chemical environments it is sometimes possible to achieve anodic protection, passing a current which takes electrons out of the metal and raises its potential. Initially this stimulates anodic corrosion, but in favourable circumstances this will be followed by the formation of a protective oxidised passive surface film.

### **Stress corrosion cracking**

Stress corrosion cracking is cracking due to a process involving conjoint corrosion and straining of a metal due to residual or applied stresses

Corrosion can take many forms; the form that concerns us here is the interaction of corrosion and mechanical stress to produce a failure by cracking. This type of failure is known as stress corrosion cracking, often abbreviated to SCC

SCC is an insidious form of corrosion; it produces a marked loss of mechanical strength with little metal loss; the damage is not obvious to casual inspection and the stress corrosion cracks can trigger mechanical fast fracture and catastrophic failure of components and structures.

SCC is not an inevitable process, and for most metals in most environments it will not occur. We can therefore identify specific combinations of metal and environment that are subject to the problem. Unfortunately, of course, as time goes by we identify more and more such combinations, especially as engineers strive to use materials more efficiently by increasing working stresses and using less expensive materials.

### **Heat Treatment**

Heat Treatment is the controlled heating and cooling of metals to alter their physical and mechanical properties without changing the product shape. Heat treatment is sometimes done inadvertently due to manufacturing processes that either heat or cool the metal such as welding or forming. Heat Treatment is often associated with increasing the strength of material, but it can also be used to alter certain manufacturability objectives such as improve machining, improve formability, restore ductility after a cold working operation. Thus it is a very enabling manufacturing process that can not only help other manufacturing process, but can also improve product performance by increasing strength or other desirable characteristics.


Steels are particularly suitable for heat treatment, since they respond well to heat treatment and the commercial use of steels exceeds that of any other material. Steels are heat treated for one of the following reasons:

1. Softening
2. Hardening
3. Material modification

**Softening:** Softening is done to reduce strength or hardness, remove residual stresses, improve toughness, restore ductility, refine grain size or change the electromagnetic properties of the steel. Restoring ductility or removing residual stresses is a necessary operation when a large amount of cold working is to be performed, such as in a cold-rolling operation or wire drawing. Annealing — full Process, spheroidizing, normalizing and tempering austempering, martempering are the principal ways by which steel is softened.

**Hardening:** Hardening of steels is done to increase the strength and wear properties. One of the pre-requisites for hardening is sufficient carbon and alloy content. If there is sufficient Carbon content then the steel can be directly hardened. Otherwise the surface of the part has to be Carbon enriched using some diffusion treatment hardening techniques.

**Material Modification:** Heat treatment is used to modify properties of materials in addition to hardening and softening. These processes modify the behavior of the steels in a beneficial manner to maximize service life, e.g., stress relieving, or strength properties, e.g., cryogenic treatment, or some other desirable properties



HEAT TREATMENT PROCESS

Full annealing is the process of slowly raising the temperature about 50 °C (90 °F) above the Austenitic temperature line A<sub>3</sub> or line A<sub>cm</sub> in the case of Hypoeutectoid steels (steels with <0.77% Carbon) and 50 °C (90 °F) into the Austenite-Cementite region in the case of Hypereutectoid steels (steels with > 0.77% Carbon).

It is held at this temperature for sufficient time for all the material to transform into Austenite or Austenite-Cementite as the case may be. It is then slowly cooled at the rate of about 20 °C/hr (36°F/hr) in a furnace to about 50 °C (90 °F) into the Ferrite-Cementite range. At this point, it can be cooled in room temperature air with natural convection. The grain structure has coarse Pearlite with ferrite or Cementite (depending on whether hypo or hyper eutectoid). The steel becomes soft and ductile.

Normalizing is the process of raising the temperature to over 60 °C (108 °F), above line A<sub>3</sub> or line A<sub>cm</sub> fully into the Austenite range. It is held at this temperature to fully convert the structure into Austenite, and then removed from the furnace and cooled at room temperature under natural convection. This results in a grain structure of fine Pearlite with excess of Ferrite or Cementite.

The resulting material is soft; the degree of softness depends on the actual ambient conditions of cooling. This process is considerably cheaper than full annealing since there is not the added cost of controlled furnace cooling.

Process Annealing is used to treat work-hardened parts made out of low-Carbon steels (< 0.25% Carbon). This allows the parts to be soft enough to undergo further cold working without fracturing. Process annealing is done by raising the temperature to just below the Ferrite-Austenite region, line A<sub>1</sub> on the diagram. This

temperature is about 727 °C (1341 °F) so heating it to about 700 °C (1292 °F) should suffice. This is held long enough to allow recrystallization of the ferrite phase, and then cooled in still air. Since the material stays in the same phase throughout the process, the only change that occurs is the size, shape and distribution of the grain structure. This process is cheaper than either full annealing or normalizing since the material is not heated to a very high temperature or cooled in a furnace.

Stress Relief Anneal is used to reduce residual stresses in large castings, welded parts and cold formed parts. Such parts tend to have stresses due to thermal cycling or work hardening. Parts are heated to temperatures of up to 600 - 650 °C (1112 - 1202 °F), and held for an extended time (about 1 hour or more) and then slowly cooled in still air.

Tempering is a process done subsequent to quench hardening. Quench-hardened parts are often too brittle. This brittleness is caused by a predominance of Martensite. This brittleness is removed by tempering. Tempering results in a desired combination of hardness, ductility, toughness, strength, and structural stability. Tempering is not to be confused with tempering on rolled stock—these tempers are an indication of the degree of cold work performed.

The mechanism of tempering depends on the steel and the tempering temperature. The prevalent Martensite is a somewhat unstable structure. When heated, the Carbon atoms diffuse from Martensite to form a carbide precipitate and the concurrent formation of Ferrite and Cementite, which is the stable form. Tool steels for example, lose about 2 to 4 points of hardness on the

Rockwell C scale. Even though a little strength is sacrificed, toughness (as measured by impact strength) is increased substantially. Springs and such parts need to be much tougher — these are tempered to a much lower hardness.

Tempering is done immediately after quench hardening. When the steel cools to about 40 °C (104 °F) after quenching, it is ready to be tempered. The part is reheated to a temperature of 150 to 400 °C (302 to 752 °F). In this region a softer and tougher structure Troostite is formed.

Alternatively, the steel can be heated to a temperature of 400 to 700 °C (752 to 1292 °F) that results in a softer structure known as Sorbite. This has less strength than Troostite but more ductility and toughness. The heating for tempering is best done by immersing the parts in oil, for tempering up to 350 °C (662 °F) and then heating the oil with the parts to the appropriate temperature. Heating in a bath also ensures that the entire part has the same temperature and will undergo the same tempering. For temperatures above 350 °C (662 °F) it is best to use a bath of nitrate salts. The salt baths can be heated up to 625 °C (1157 °F). Regardless of the bath, gradual heating is important to avoid cracking the steel. After reaching the desired temperature, the parts are held at that temperature for about 2 hours, then removed from the bath and cooled in still air.

### Hardening

Hardness is a function of the Carbon content of the steel. Hardening of a steel requires a change in structure from the body-centered cubic structure found at room temperature to the face-centered cubic structure found in the Austenitic region. The steel is heated to Austenitic region. When suddenly quenched, the Martensite is formed. This is a very strong and brittle structure. When slowly quenched it would form Austenite and Pearlite which is a partly hard and partly soft structure. When the cooling rate is extremely slow then it would be mostly Pearlite which is extremely soft.

Usually when hot steel is quenched, most of the cooling happens at the surface, as does the hardening. This propagates into the depth of the material. Alloying helps in the hardening and by determining the right alloy one can achieve the desired properties for the particular application.



AUSTENITE



MARTENSITE



CEMENTITE



PEARLITE  
COARSE



PEARLITE  
FINE

## ALUMINIUM ALLOYS

- WROUGHT ALUMINIUM ALLOYS
  - Al-Zn-Mg-Cu superalloys and high-strength alloys
  - Long-life aluminium alloys
  - High-workable weldable corrosion-resistant aluminium alloys
  - Al-Li alloys with lowered density
  - Heat-resistant alloys
  - SiAl-type laminates

## CASTABLE ALUMINIUM ALLOYS

- High strength castable aluminium alloys
- Castable heat-resistant aluminium alloys
- Weldable corrosion-resistant aluminium alloys

## TITANIUM ALLOYS

- WROUGHT TITANIUM ALLOYS
  - Heat-resistant titanium alloys for GTE components
  - Structural titanium alloys
  - High strength structural titanium alloys
  - Intermetallic titanium alloys
- CASTABLE TITANIUM ALLOYS

- **MAGNESIUM ALLOYS**

- **WROUGHT MAGNESIUM ALLOYS**

- Medium-strength alloys
    - High-strength alloys
    - Granulated alloys
    - Heat-resistant alloy
    - Ultra-light alloys (alloys with lowered density)

- **CASTABLE MAGNESIUM ALLOYS**

- Mg–Zn–Zr High-strength alloys
    - Mg–Al–Zn corrosion-resistant alloys
    - Mg–REM–Zr heat-resistant alloys
    - Antiburining-on adding materials

Magnetic alloys and intermetallics are metallic materials capable of producing a constant magnetic field for a prolonged period of time. There are only a limited number of chemical elements that can produce alloys with permanent magnetic properties at ambient temperature; Fe, Ni, Co and rare earth metals are the most important ones.

1. Samarium-Cobalt Alloys
2. Aluminium-Nickel-Cobalt Alloys
3. Neodymium-Iron-Boron Alloys

### Effects of Alloying Elements in Steel

Alloying elements are added to effect changes in the properties of steels. The basis of this section is to cover some of the different alloying elements added to the basic system of iron and carbon, and what they do to change the properties or effectiveness of steel.

### Carbon

As I've already stated, the presence of carbon in iron is necessary to make steel. Carbon is essential to the formation of cementite (as well as other carbides), and to the formation of pearlite, spheroidite, bainite, and iron-carbon martensite, with martensite being the hardest of the micro-structures, and the structure sought after

by knifemakers. The hardness of steel (or more accurately, the hardenability) is increased by the addition of more carbon, up to about 0.65 percent. Wear resistance can be increased in amounts up to about 1.5 percent. Beyond this amount, increases of carbon reduce toughness and increase brittleness. The steels of interest to knifemakers generally contain between 0.5 and 1.5 percent carbon. They are described as follows:

- Low Carbon: Under 0.4 percent
- Medium Carbon: 0.4 - 0.6 percent
- High Carbon: 0.7 - 1.5 percent

Carbon is the single most important alloying element in steel.

### Chromium

As with manganese, chromium has a tendency to increase hardness penetration. This element has many interesting effects on steel. When 5 percent chromium or more is used in conjunction with manganese, the critical quenching speed is reduced to the point that the steel becomes air hardening. Chromium can also increase the toughness of steel, as well as the wear resistance. Probably one of the most well known effects of chromium on steel is the tendency to resist staining and corrosion. Steels with 14 percent or more chromium are referred to as stainless steels. A more accurate term would be stain resistant. Stainless tool steels will in fact darken and rust, just not as readily as the non-stainless varieties. Steels with chromium also have higher critical temperatures in heat treatment.

### Nickel

Nickel increases the strength of ferrite, therefore increasing the strength of the steel. It is used in low alloy steels to increase toughness and hardenability. Nickel also tends to help reduce distortion and cracking during the quenching phase of heat treatment.

### Molybdenum

Molybdenum increases the hardness penetration of steel, slows the critical quenching speed, and increases high temperature tensile strength.

### Vanadium

Vanadium helps control grain growth during heat treatment. By inhibiting grain growth it helps increase the toughness and strength of the steel.

## Tungsten

Used in small amounts, tungsten combines with the free carbides in steel during heat treatment, to produce high wear resistance with little or no loss of toughness. High amounts combined with chromium gives steel a property known as red hardness. This means that the steel will not lose its working hardness at high temperatures. An example of this would be tools designed to cut hard materials at high speeds, where the friction between the tool and the material would generate high temperatures.

## Copper

The addition of copper in amounts of 0.2 to 0.5 percent primarily improves steel's resistance to atmospheric corrosion. It should be noted that with respect to knife steels, copper has a detrimental effect to surface quality and to hot-working behavior due to migration into the grain boundaries of the steel.

## Niobium

In low carbon alloy steels Niobium lowers the transition temperature and aids in a fine grain structure. Niobium retards tempering and can decrease the hardenability of steel because it forms very stable carbides. This can mean a reduction in the amount of carbon dissolved into the austenite during heat treating.

## Boron

Boron can significantly increase the hardenability of steel without loss of ductility. Its effectiveness is most noticeable at lower carbon levels. The addition of boron is usually in very small amounts ranging from 0.0005 to 0.003 percent.

## Titanium

This element, when used in conjunction with Boron, increases the effectiveness of the

Boron in the hardenability of steel.